

Art	Verschiebung	Förderleistung		Druck	Max. Umdrehungen	Abmessungen										
		@ 1500 U / min	@ max. U / min			Pnom	n	EIN	B	Einlass			Auslauf			
	cm <sup>3</sup> / Umdrehung	l / min	l / min	Bar	U / min	mm	mm	E	d	F	E	d	F			
<b>30A (C) 20X146</b>	20	28.2	56.4	250	3000	56.1	116.7	40	M8	19	40	M8	19			
30A (C) 22.2X146	22.5	31.7	63.5	250	3000	57.6	119.7									
30A (C) 25X146	25	35.3	70.5	250	3000	58.3	121.1									
30A (C) 28X146	28	39.5	79	250	3000	60.2	124.7									
30A (C) 32X146	32	45.1	90.2	250	3000	66.5	137.3	51	M10	27				40	M8	19
30A (C) 36X146	36	51.3	95.8	250	2800	68	140.5									
30A (C) 42X146	42	59.9	99.8	230	2500	70.8	146.1									
30A (C) 46X146	46	65.6	100.5	230	2300	72.7	149.8									
30A (C) 50X146	50	71.3	99.8	200	2100	74.5	153.4									
30A (C) 55X146	55	78.4	91.4	200	1750	76.7	157.9									
30A (C) 60X146	60	85.5	99.8	180	1750	78.7	162.4									

